

# ALKACLEAN HD/ PC CLEANER/HIGH FOAM

## APPLICATIONS

ALKACLEAN HD/PC CLEANER HIGH FOAM is used for removal of Coal, Pet Coke, vegetable, Oily Residues, Sulfur, Concentrates and animal oil residues in cargo tanks. It is also used as a final treatment for cleaning tanks from black to white or grain.

ALKACLEAN HD/PC CLEANER HIGH FOAM is suitable for use on ferrous metal, including stainless steel epoxy tank coatings.

ALKACLEAN HD/PC CLEANER/HIGH FOAM is used for cleaning boiler furnace and as a neutralizing agent.

## DIRECTIONS FOR USE TANK CLEANING CARGO CLEANING

Tankcleaning should, if possible, be carried out immediately after discharge of cargo. ALKACLEAN HD/PC CLEANER/HIGH FOAM should be applied with water at a temperature above 60°C if possible. The cleaning should be done by circulation using tank cleaning machine, spray equipment or injected into the steam.

### QUICK DRYING OILS

Use a 3% to 5% solution of ALKACLEAN HD/PC CLEANER/HIGH FOAM with fresh water.

### SEMI-DRYING OILS

Use a 5% solution of ALKACLEAN HD/PC CLEANER/HIGH FOAM with fresh water.

**NOTE:** Fresh water solutions are recommended. If seawater solution is used, it is recommended that dosage amount be increased by 1.5 times the amount required for fresh water solutions.

**NOTE:** While cleaning semi dry oils like Coal or Pet Coke and after washing, some times we noticed that white stripes or white stains are remaining on the surface of the Cargo Holds. In such cases we recommend a washing with fresh water with 1-2% rust remover. This procedure can take place during the last washing of the cargo hold to save time for all.

## BOILER FURNACE CLEANING

Use a 10% to 20% solution of ALKACLEAN HD/PC CLEANER/ HIGH FOAM with fresh water.

A hot solution of more than 40° C is preferable as treatment is more effective when heated. Apply solution to surfaces to be cleaned by spraying. Depending on the nature, age and state of the deposits, repeat spraying as necessary. For deposits, which are very hard to remove a solution of up to 50% can be used.

## CLEANING OIL CONTAMINATION IN BOILERS & HEAT EXCHANGERS WATER SIDE

Generally the amount of ALKACLEAN HD/PC CLEANER/HIGH FOAM required is 4%of the unitcapacity depending on the degree of contamination. The above dosage may may be increased to 5-10%.

Code: 161161421

## ALKACLEAN HD / PC CLEANER / HIGH FOAM

Heavy duty alkaline cleaner

- Removes hardened oxidized oil and grease deposits
- Effective liquid product for pet coke removal
- Cleaning of boiler furnace Removes vegetable, fish and animal oils
- Final treatment for cleaning cargo tanks from black to white or grain
- Safe on epoxy and polyurethane tank coatings IMO approved & biodegradable, minimizing environmental concerns.

## PRODUCT CHARACTERISTICS

**Appearance:** clear amber liquid

**Corrosive action:** avoid contact with aluminum, zinc, tin and their alloys

**Specific gravity:** 1,3 (20°C)  
pH: >13

**Flash point:** none

**IMO Class:** 8/11

**UN Number:** 1824  
ADR: 8.42b)

## ALKACLEAN HD/ PC CLEANER/HIGH FOAM



### PROCEDURE

- Blank off unit to be certain that it is isolated
- Drain unit of all water
- Connect steam hose, preferably to bottom of unit
- Connect re-circulating pump, if possible. If not, use steam for agitation, vent unit at highest possible point to prevent pressure build-up and allow fumes to escape
- Pour 4% ALKACLEAN HD/PC CLEANER/HIGH FOAM into the unit
- Add fresh water to the top of tube bundle level or minimum water level for boilers.
- Heat solution to at least 60°C (140°F) and re-circulate for a minimum of 20 to 24 hours after this temperature is attained
- After heating and re-circulation or agitation, dump the solution from the unit
- For boilers, flush each tube with fresh water in order to remove oil residues

### NATURE OF SPECIAL RISKS AND SAFETY ADVICE

In accordance with the latest EEC Council directives this product is subjected to:

R35	Causes severe burns
S2	Keep out of reach of children
S26	In case of contact with eyes, rinse
S27	Immediately take off all contaminated clothing
S36/37/39	Wear suitable protective clothing
S46	In case of accident or if you feel unwell, seek medical advice immediately (show the label if possible)