

Return Clamp Assembly 200A With Dix 70

Item No.: 361362919

Product information

200A return clamp assembly with DIX 70 connector, has a 35mm² 3m cable. According to the Code of Safe Working Practices for Merchant Seafarers (COSWP, UK): 24.7.3 Earth return clamp should be connected as closest as possible to welding piece and not to the hull. The return clamp should always be placed as close as possible to the welding area, or on the work piece itself if this is not an integral part of the hull. The welding current load to be used, must have good contact, so the return connector must be properly dimensioned to provide good quality of contact. We provide all four types of return clamps: the 200A, the 400A, the 600A and the 800A.



Features

- Strong grip that permits attachment to any work piece
- Provide a large contact area with less overheating
- Good contact with the workpiece

Benefits

- Secured return on work piece reduces circuit resistance and provide a stable voltage which ensures good welding quality
- Compliance to OCIMF SIRE 2.0 electric arc welding safety requirements

Specification

General:

Invent Hazard Material (IMO/EU) classification	NA
--	----